APPENDIX C

Representative Site Photos

Appendix C – Site Photographs



Photo 1. Photo show PEM (foreground) and PSS (background) portions of Wetland A.



Photo 2. Photo shows typical conditions in PSS portion of Wetland A.



Photo 3. Photo shows typical conditions in PEM portions of Wetland A.



Photo 4. Photo shows Wetland B looking through adjacent upland buffer. Similar conditions exist in Wetland C, D, and E.





Photo 5. Photo shows Stream 1 at PIP.



Photo 6. Photos shows typical conditions in offsite portion of Stream 3 (combined channel of Stream 3a and 3b) at the Chair 4 Road.


APPENDIX D


Final SEIS Figure 17



Mt. Spokane Final SEIS

ALTERNATIVE 3: Impacts to Wetland and Stream Buffers Figure 17





Proposed Ski Lift Clearing (61.9 acres)

Clearing and Grading (12.4 acres) Grading (0.5 acres) Existing Roads

- Existing Streams 75' Riparian Buffer
Existing Wetlands
60' Wetland Buffer



Mt. Spokane Ski and Snowboard Resort Spokane, Washington, USA

SEGROUP